

TABLE 6
SUMMARY OF PCB ANALYTICAL RESULTS FOR
PAINT, CAULKING AND WINDOW GLAZING
BALDWIN HARDWARE MANUFACTURING CORP.
READING, PENNSYLVANIA

Sample ID	Sample Description	Sample Location	PCB Content (mg/kg)	
			Aroclor -1254	Aroclor-1268
AB-002	Gray caulk on wide flange column in concrete block wall	Building 2A south wall	3.94	6.72
AB-066	Caulk on wide flange column	North exterior wall of Building 50	BRL	BRL
AB-085	Factory Office Building window glazing	South side of Factory Office Building. First floor	BRL	BRL
AB-086	Caulk on metal window frame	South side of Factory Office Building at roof level. First floor	BRL	BRL
AB-093	Dark grey in expansion points of brick façade	West exterior wall of Building 3	BRL	BRL
AB-095	Caulk on metal frame windows	East facing windows above Building 8 Receiving Area	2.99	BRL
AB-096	Window Glazing	East facing windows above Building 8 Receiving Area	BRL	BRL
AB-100	Tan caulk in expansion joint for concrete block wall	North exterior wall of Building 9	10.50	BRL
AB-112	Caulk in expansion joints for concrete block wall	Attached building at Southeast corner of Building 50	BRL	BRL
AB-114	Multi-layered caulk in 1" wide expansion joint for masonry façade	Southwest side of Building 50	BRL	BRL
AB-115	Tan caulk on edges of wide flange column in exterior concrete block wall	East exterior wall of tunnel enclosure	2,350	8,420
AB-121	Tan caulk edges of wide flange column	South interior wall of tunnel enclosure near Building 51	82.5	6.16
PC-01	Red Paint	Painted floor near Building 12 vapor degreaser	BRL	BRL
CC-03-006	Gray painted flooring/concrete chip	Building 3	BRL	BRL
CC-03-007	Gray painted flooring/concrete chip	Building 3	0.072	BRL
CC-07-005	Gray painted flooring/concrete chip	Building 7	BRL	BRL
CC-08-007	Gray painted flooring/concrete chip	Building 8	BRL	BRL
CC-08-008	Gray painted flooring/concrete chip	Building 8	BRL	BRL
CC-10-002	Gray painted flooring/concrete chip	Building 10	BRL	BRL
CC-10-005	Gray painted flooring/concrete chip	Building 10	BRL	BRL
CC-11-006	Gray painted flooring/concrete chip	Building 11	BRL	BRL

Notes:

BRL - Below Reporting Limit